



DRAWINGS


1A - Undamaged




1B - Damaged by Chafing



1C - Damaged by Incision



1D - Damaged by Solvents



1E - Damaged by Corrosive Gas




FIG. 1




FIG. 2A




FIG. 2C




FIG. 2B




FIG. 3




FIG. 4

